

(5)

**Office of The Sub Division Officer
PWD Distt. Sub Division No.1, Indore**

S.No. 318

/SAC/2025-26

Date: 19-5-2025

Annexure D

BUILDING SAFETY CERTIFICATE

It is certified that the existing building **Vidyasagar School At Bicholi Mardana, Indore (MP)** is having block(s)/Floor(s) as per details below:

Detail of Block(s) in School	Block (1)	Block (2)	Block (3)	Block (4)	Block (5)	Block (6)
No. of Floor(s) in the Block	G+2	-	-	-	-	-

The building is owned/occupied by **Vidyasagar School** have complied with the Building safety requirements in accordance with National Building code Rules, and verified by the officers concerned of **Public Work Department Sub Division No.1, Indore (MP)** (Name of Department/Govt.) on **19/05/2025** (date of inspection) in the presence of **Principal, Mrs Bhavana Pujari** and that the building/premises is fit for occupancy for running school with effect from **19/05/2025** for a period of 01 years in accordance with rule and subject to compliance of the specific conditions as appended.

Issued on **19/05/2025** at Indore by **Sub Divisional Officer PWD, Indore**

Danny
Sub Divisional Officer
PWD Distt. Sub Division No.1, Indore
Sub Divisional Officer
P.W.D. (B&R) Dist. Sub Dn. No. 1, INDORE